Norm Pipe Clamps&Fixing Elements Industry&Trading Ltd.Co			TENSILE TEST REPORT		Date:31.07.2013 Page: 1/2	
TYPE	SIZE	SAMPLE NO	LOAD VALUE AT FRACTURE MENTIONED IN THE CATALOGUEİ(kN)	LOAD VALUE AT FRACTURE OBSERVED BY THE TEST (kN)	DEFORMATION TYPE	
NKSC 006	1/8"	1	3,9	5,335	Side Screw was clamped off	
NKSC 006	1/8"	2	3,9	6,275	Side Screw was clamped off	
NKSC 006	1/8"	3	3,9	6,025	Side Screw was clamped off	
NSC 006	1/8"	1	3,9	6,020	Side Screw was clamped off	
NSC 006	1/8"	2	3,9	5,590	Nut was broken from clamps	
NSC 006	1/8"	3	3,9	5,055	Nut was broken from clamps	
NSC 008	1/4"	1	3,9	5,300	Nut was broken from clamps	
NSC 008 *	1/4"	2	3,9	5,895	Nut was broken from clamps	
NSC 008	1/4"	3	3,9	6,130	Side Screw was clamped off	
NKSC 008	1/4"	1	3,9	6,005	Side Screw was clamped off	
NKSC 008	1/4"	2	3,9	5,365	Side Screw was clamped off	
NKSC 008	1/4"	3	3,9	6,020	Side Screw was clamped off	
NKSC 010	3/8"	1	3,9	5,290	Combi Nut was broken from clamps	
NKSC 010	3/8"	2	3,9	4,335	Combi Nut was broken from clamps	
NKSC 010	3/8"	3	3,9	4,440	Combi Nut was broken from clamps	
NSC 010	3/8"	1	3,9	4,370	Nut was broken from clamps	
NSC 010	3/8"	2	3,9	5,025	Nut was broken from clamps	
NSC 010	3/8"	3	3,9	4,545	Nut was broken from clamps	
NSC 015	1/2"	1	3,9	5,445	Nut was broken from clamps	
NSC 015	1/2"	2	3,9	4,290	Nut was broken from clamps	
NSC 015	1/2"	3	3,9	5,055	Nut was broken from clamps	
NKSC 015	1/2"	1	3,9	5,745	Side Screw was clamped off	
NKSC 015	1/2"	2	3,9	5,890	Side Screw was clamped off	
NKSC 015	1/2"	3	3,9	5,610	Side Screw was clamped off	
NKSC 020	3/4"	1	3,9	5,390	Combi Nut was broken from clamps	
NKSC 020	3/4"	2	3,9	5,410	Side Screw was clamped off	
NKSC 020	3/4"	3	3,9	5,225	Side Screw was clamped off	
NSC 020	3/4"	1	3,9	4,310	Nut was broken from clamps	
NSC 020	3/4"	2	3,9	4,245	Nut was broken from clamps	
NSC 020	3/4"	3	3,9	5,260	Side Screw was clamped off	
NSC 025	1"	1	3,9	5,010	Nut was broken from clamps	
NSC 025	1"	2	3,9	4,325	Nut was broken from clamps	
NSC 025	1"	3	3,9	5,170	Side Screw was clamped off	
NKSC 025	1"	1	3,9	5,665	Side Screw was clamped off	
NKSC 025	1"	2	3,9	5,720	Side Screw was clamped off	
NKSC 025	1"	3	3,9	5,425	Side Screw was clamped off	
NKSC 032	1 1/4"	1	4,8	6,735	Side Screw was clamped off	
NKSC 032	1 1/4"	2	4,8	5,360	Combi Nut was broken from clamps	
NKSC 032	1 1/4"	3	4,8	6,885	Side Screw was clamped off	
NSC 032	1 1/4"	1	4,8	7,260	Side Screw was clamped off	
NSC 032	1 1/4"	2	4,8	6,890	Pipe clamp was broken	
NSC 032	1 1/4"	3	4,8	5,460	Side Screw was clamped off	
NSC 040	1 1/2"	1	4,8	5,395	Nut was broken from clamps	
NSC 040	1 1/2"	2	4,8	6,040	Side Screw was clamped off	
NSC 040	1 1/2"	3	4,8	6,620	Side Screw was clamped off	
NKSC 040	1 1/2"	1	4,8	5,325	Combi Nut was broken from clamps	
NKSC 040	1 1/2"	2	4,8	5,195	Pipe clamp was broken	
NKSC 040	1 1/2"	3	4,8	5,145	Side Screw was clamped off	
NKSC 050	2"	1	4,8	6,245	Side Screw was clamped off	
NKSC 050	2"	2	4,8	6,655	Side Screw was clamped off	
NKSC 050	2"	3	4,8	7,125	Side Screw was clamped off	
NSC 050	2"	1	4,8	6,260	Pipe clamp was broken	
NSC 050	2"	2	4,8	6,760	Side Screw was clamped off	
NSC 050	2"	3	4,8	7,055	Side Screw was clamped off	
NSC 065	2 1/2"	1	6,9	9,350	Side Screw was clamped off	
NSC 065	2 1/2"	2	6,9	9,635	Side Screw was clamped off	
NSC 065	2 1/2"	3	6,9	8,270	Side Screw was clamped off	
NKSC 065	2 1/2"	1	6,9	7,710	Combi Nut was broken from clamps	
NKSC 065	2 1/2"	2	6,9	8,025	Side Screw was clamped off	
NKSC 065	2 1/2"	3	6,9	9,480	Combi Nut was broken from clamps	
NKSC 080	3"	1	6,9	8,680	Side Screw was broken	
NKSC 080	3"	2	6,9	9,610	Combi Nut was broken from clamps	
NKSC 080	3"	3	6,9	7,730	Combi Nut was broken from clamps	
NSC 080	3"	1	6,9	10,340	Side Screw was clamped off	
NSC 080	3"	2	6,9	8,750	Side Screw was clamped off	
NSC 080	3"	3	6,9	7,915	Side Screw was broken	
1400 000	3	The second second second	0,7	1,710	Dide Delett tras blokeli	



Norm Pipe Clamps&Fixing Elements Industry&Trading Ltd.Co			TENSILE TEST REPORT		Page: 2/2
ТҮРЕ	SIZE	SAMPLE NO	LOAD VALUE AT FRACTURE MENTIONED IN THE CATALOGUEI(kN)	LOAD VALUE AT FRACTURE OBSERVED BY THE TEST (kN)	DEFORMATION TYPE
NSC 100	4"	1	6,9	8,075	Side Screw was clamped off
NSC 100	4"	2	6,9	7,215	Side Screw was clamped off
NSC 100	4"	3	6,9	10,555	Side Screw was clamped off
NKSC 100	4"	1	6,9	9,985	Combi Nut was broken from clamps
NKSC 100	4"	2	6,9	9,890	Combi Nut was broken from clamps
NKSC 100	4"	3	6,9	9,770	Combi Nut was broken from clamps
NKSC 125	5"	1	7,8	8,005	Side Screw was broken
NKSC 125*	5"	2	7,8	8,325	Side Screw was broken
NKSC 125	5"	3	7,8	8,365	Side Screw was broken
NSC 125	5"	1	7,8	8,280	Side Screw was broken
NSC 125	5"	2	7,8	9,100	Side Screw was broken
NSC 125	5"	3	7,8	8,605	Side Screw was broken
NSC 150	6"	1	7,8	7,960	Side Screw was broken
NSC 150	6"	2	7,8	8,440	Side Screw was broken
NSC 150	6"	3	7,8	8,750	Side Screw was broken
NKSC 150	6"	1	7,8	8,480	Side Screw was clamped off
NKSC 150	6"	2	7,8	7,905	Side Screw was broken
NKSC 150	6"	3	7,8	8,720	Side Screw was clamped off
NKSC 200	8"	1	7,8	8,630	Side Screw was clamped off
NKSC 200	8"	2	7,8	8,550	Side Screw was clamped off
NKSC 200	8"	3	7,8	9,320	Side Screw was broken
NSC 200	8"	1	7,8	8,575	Side Screw was clamped off
NSC 200	8"	2	7,8	8,860	Side Screw was clamped off
NSC 200	8"	3	7,8	9,130	Side Screw was clamped off
pproved by: ate: ignature:				Approved by: Date: 3(107)[3] Signature:	€ TY